

## Durometer Hardness Conversion Table

	<b>Durometer Type Scale</b>					
	<b>Shore A</b>	<b>Shore B</b>	<b>Shore C</b>	<b>Shore D</b>	<b>Shore O</b>	<b>Shore OO</b>
<b>Shore Hardness Value</b>	100	85	77	58		
	95	81	70	46		
	90	76	59	39		
	85	71	52	33		
	80	66	47	29	84	98
	75	62	42	25	79	97
	70	56	37	22	75	95
	65	51	32	19	72	94
	60	47	28	16	69	93
	55	42	24	14	65	91
	50	37	20	12	61	90
	45	32	17	10	57	88
	40	27	14	8	53	86
	35	22	12	7	48	83
	30	17	9	6	42	80
	25	12			35	76
	20	6			28	70
	15				21	62
	10				14	55
5				8	45	

**Note:** The hardness values listed above are approximate and should only be used as a durometer selection guide. Physical tests by the end user are the only accurate way of ensuring proper product selection.